



Metal Forming Processes — ME5807

Dr. Yogesh Kumar

Department of Mechanical Engineering
National Institute of Technology Patna, Bihar, India - 800 005

Email: yogesh.me@nitp.ac.in

Tel: +91-9410478242

7 September 2020

Outlines

Temperature in Metal Forming

Strain Rate



Lecture No. 2

7 September 2020



Tensile Test / Properties - True Stress-Strain

$$\text{True Stress, } \sigma = \frac{F}{A}$$

$$\text{True Strain, } \epsilon = \ln \frac{l}{l_0}$$



Tensile Test / Properties - True Stress-Strain

$$\text{True Stress, } \sigma = \frac{F}{A}$$

$$\text{True Strain, } \epsilon = \ln \frac{l}{l_0}$$




Figure: True Stress Strain



Tensile Test / Properties - True Stress-Strain




Figure: True Stress Strain

The stress-strain curve can be represented as,

$$\sigma = K\epsilon^n \quad (1)$$

K = is the strength coefficient,
 n = strain hardening / work hardening exponent.



Tensile Test / Properties - True Stress-Strain




Figure: True Stress Strain




Figure: True Stress Strain - Logarithmic



Tensile Test / Properties - True Stress-Strain

- ▶ Equation 1 is called as the flow curve.
- ▶ Behaviour of metals in plastic zone.
- ▶ capacity for cold strain hardening.
- ▶ the logarithmic plot of flow curve is straight line.
- ▶ the slope of straight line is equal to the exponent n .
- ▶ $n = 0$ for perfectly plastic solid, and $n = 1$ for perfectly elastic solid.
- ▶ for most of the metals, n has values between 0.10 and 0.50.



Flow Stress

Material Factors:

- ▶ Purity of the material,
- ▶ Cristal Structure,
- ▶ Grain Size,
- ▶ Heat Treatment of the materials.

Process Factors:

- ▶ Strain,
- ▶ Strain rate,
- ▶ Temperature.




Figure: Effect of temperature on flow stress



Flow Stress Curve and Average Flow Stress

- ▶ Flow stress curve, $\sigma_f = K\epsilon^n$
- ▶ Flow stress curve based on true stress and true strain.
- ▶ Average Flow stress,

$$\sigma_m = \frac{K\epsilon_{max}^n}{1+n}$$




Figure: Flow curve during cold-forming



Temperature in Metal Forming

- ▶ For any metal, K and n in the flow curve depend on temperature
 1. Both strength (K) and strain hardening (n) are reduced at higher temperatures
 2. In addition, ductility is increased at higher temperatures

- ▶ Three temperature ranges in metal forming:
 1. Cold Working / Cold Forming,
 2. Warm Working / Warm Forming,
 3. Hot Working / Hot Forming.



Cold Working

- ▶ Performed at room temperature or slightly above
- ▶ Many cold forming processes are important mass production operations
- ▶ Minimum or no machining usually required
 - ▶ These operations are near net shape or net shape processes.



Advantages of Cold Working

- ▶ Better accuracy, closer tolerances
- ▶ Better surface finish
- ▶ No heating of work required
- ▶ Strain hardening increases strength and hardness
- ▶ Grain flow during deformation can cause desirable directional properties in product



Disadvantages of Cold Working

- ▶ Higher forces and power required in the deformation operation
- ▶ Surfaces of starting workpiece must be free of scale and dirt
- ▶ Ductility and strain hardening limit the amount of forming that can be done
 - ▶ In some cases, metal must be annealed to allow further deformation
 - ▶ In other cases, metal is simply not ductile enough to be cold worked



Warm Working

- ▶ Performed at temperatures above room temperature but below recrystallization temperature
- ▶ Dividing line between cold working and warm working often expressed in terms of melting point:

$$0.3T_m < T < 0.5T_m$$

Advantages of Warm Working

- ▶ Lower forces and power than in cold working
- ▶ More intricate work geometries possible
- ▶ Need for annealing may be reduced or eliminated
- ▶ Low spring back



Hot Working

- ▶ Deformation at temperatures above the recrystallization temperature
- ▶ Recrystallization temperature = about one-half of melting point on absolute scale
 - ▶ In practice, hot working usually performed somewhat above $0.5T_m$
 - ▶ Metal continues to soften as temperature increases above $0.5T_m$, enhancing advantage of hot working above this level



Why Hot Working?

Capability for substantial plastic deformation of the metal - far more than possible with cold working or warm working

- ▶ **Why?**
 - ▶ Strength coefficient (K) is substantially less than at room temperature
 - ▶ Strain hardening exponent (n) is zero (theoretically)
 - ▶ Ductility is significantly increased



Advantages of Hot Working

- ▶ Workpart shape can be significantly altered
- ▶ Lower forces and power required
- ▶ Metals that usually fracture in cold working can be hot formed
- ▶ No strengthening of part occurs from work hardening
 - ▶ Advantageous in cases when part is to be subsequently processed by cold forming



Disadvantages of Hot Working

- ▶ Lower dimensional accuracy
- ▶ Higher total energy required (due to the thermal energy to heat the workpiece)
- ▶ Work surface oxidation (scale), poorer surface finish Shorter tool life



Strain Rate

- ▶ The strain rate is the rate at which the deformation occurs, i.e., deformation or strain per time unit.
- ▶ This is equivalent to the instantaneous strain (or change in strain) per time unit.

$$\dot{\epsilon} = \frac{\Delta\epsilon}{\Delta t}$$



Effect of Strain rate on Flow Stress

The effect of strain rate on the flow stress σ_f at a fixed strain and temperature,

$$\sigma_m = C\dot{\epsilon}^m$$

C = strength coefficient (similar but not equal to the strength coefficient K,

m = strain rate sensitivity exponent.

Flow stress as a function of strain and strain rate,

$$\sigma_m = A\epsilon^n\dot{\epsilon}^m$$

A = strength coefficient (combining the effect of the coefficients K and C)

